

\$RAMWV,168.0,R,5.9,N,A*2D
\$FUZDA,183427,19,04,2016,-2,0*65
\$FURMC,183427,A,5215.2860,N,00522.8964,E,0.0,320.6,190416,1,E*67
\$GPZDA,183427,19,04,2016,0,0*4A
\$RAMWV,168.0,T,005.9,N,A*2B
\$FURMB,A,0.00,R,START,000F,314.229,N,00511.209,E,59.5,353.2,0.0,V*75
\$OSGGA,183428.00,5215.28848,N,00522.89599,E,2,10,0.90,0.2,M,46.0,M,,0000*
5F
\$RADPT,0.6,0*4B
\$RAVHW,,T,196.0,M,0.0,N,,, *2F
!OSVDM,1,1,,A,13aGt<?P00PI18>Mqdm00?vp2<0F,0*5F
\$RAHDG,194.0,,,, *56
\$FUGLL,5215.2860,N,00522.8964,E,183428,A*27
\$OSGLL,5215.28848,N,00522.89599,E,183428.00,A,D*64
\$FUGGA,183428,5215.2860,N,00522.8964,E,1,7,2.5,-5,M,37,M,, *53
\$OSGBS,183428.00,0.5,0.5,1.2,,,, *46
\$RAVWR,157.0,R,5.9,N,,,, *53
\$FUVTG,,T,320.1,M,0.0,N,0.1,K*61
\$RAMWV,157.0,R,5.9,N,A*21
\$FUZDA,183428,19,04,2016,-2,0*6A
!OSVDO,1,1,,B3aL>PP0086::@7NJ3GQ3wf5oP06,0*71
\$RAMWV,157.0,T,005.8,N,A*26
\$FURMC,183428,A,5215.2860,N,00522.8964,E,0.0,321.1,190416,1,E*6E
\$GPZDA,183428,19,04,2016,0,0*45
\$FURMB,A,0.00,R,START,000F,314.229,N,00511.209,E,59.5,353.2,0.0,V*75
!OSVDM,1,1,,A,13aDB5PP00PH`RjMqdKh0?vr26B8,0*38
\$OSGGA,183429.00,5215.28845,N,00522.89607,E,2,10,0.90,0.1,M,46.0,M,,0000*
54
\$RADPT,0.7,0*4A
\$RAVHW,,T,194.0,M,0.0,N,,, *2D
\$RAHDG,196.0,,,, *54
\$FUGLL,5215.2861,N,00522.8964,E,183429,A*27
\$OSGLL,5215.28845,N,00522.89607,E,183429.00,A,D*6C
\$FUGGA,183429,5215.2861,N,00522.8964,E,1,7,2.5,-5,M,37,M,, *53
\$RAVWR,169.5,R,5.9,N,,,, *5B
\$OSGBS,183429.00,0.5,0.5,1.2,,,, *47
!OSVDM,1,1,,A,13aOBq0P00PI18NMqifh0?vr20RS,0*54
\$RAMWV,169.5,R,5.9,N,A*29
\$FUVTG,,T,320.9,M,0.1,N,0.1,K*68
\$FUZDA,183429,19,04,2016,-2,0*6B
\$RAMWV,169.4,T,005.8,N,A*2F
\$FURMC,183429,A,5215.2861,N,00522.8964,E,0.1,321.9,190416,1,E*67
\$GPZDA,183429,19,04,2016,0,0*44
!OSVDM,1,1,,B,33aFf9gP000HEfFMsGJ00?vn0031,0*61
!OSVDM,1,1,,A,133q7FPP00PI3iDMppJP0?vt2<0?,0*4B
\$FURMB,A,0.00,R,START,000F,314.229,N,00511.209,E,59.5,353.2,0.0,V*75
!OSVDM,2,1,0,B,53aFf9T000010G?OSH1H4LD8tp@000000000001698<36t0Ht000000000
00,0*6F
!OSVDM,2,2,0,B,00000000000,2*27
\$OSGGA,183430.00,5215.28844,N,00522.89609,E,2,10,1.04,-
0.2,M,46.0,M,,0000*71
!OSVDM,1,1,,B,83aFf9Pj2d<ttL=Leib@a?aE0000,0*6F
\$RADPT,0.7,0*4A
\$RAVHW,,T,196.0,M,0.0,N,,, *2F
\$RAHDG,196.0,,,, *54
\$FUGLL,5215.2861,N,00522.8963,E,183430,A*28
\$OSGLL,5215.28844,N,00522.89609,E,183430.00,A,D*6B
\$RAVWR,167.0,R,5.9,N,,,, *50

\$RAMWV,167.0,R,5.9,N,A*22
\$FUGGA,183430,5215.2861,N,00522.8963,E,1,7,2.5,-5,M,37,M,,*5C
\$OSGBS,183430.00,0.5,0.4,1.2,09,,120.2,75.5*71
\$FUVTG,,T,321.6,M,0.1,N,0.1,K*66
\$FUZDA,183430,19,04,2016,-2,0*63
\$RAMWV,167.2,T,005.9,N,A*26
!OSVDO,1,1,,B3aL>PP0086::@WNJ3CQ3wg5oP06,0*14
\$FURMC,183430,A,5215.2861,N,00522.8963,E,0.1,322.6,190416,1,E*64
\$GPZDA,183430,19,04,2016,0,0*4C
\$FURMB,A,0.00,R,START,000F,314.229,N,00511.209,E,59.5,353.2,0.0,V*75
!OSVDM,1,1,,B,13aDr1PP00PHET0MshM@E?vtR@B@,0*4B
!OSVDM,1,1,,B,13aDpG0P00PHSnRMwAQU:gw`26B8,0*69
\$OSGGA,183431.00,5215.28841,N,00522.89613,E,2,10,1.04,-
0.4,M,46.0,M,,0000*78
\$RADPT,0.7,0*4A
\$RAVHW,,T,196.0,M,0.0,N,,, *2F
\$RAHDG,196.0,,,, *54
\$FUGLL,5215.2861,N,00522.8963,E,183431,A*29
\$RAVWR,171.5,L,5.9,N,,,, *4C
\$OSGLL,5215.28841,N,00522.89613,E,183431.00,A,D*64
\$RAMWV,188.5,R,5.9,N,A*26
\$FUGGA,183431,5215.2861,N,00522.8963,E,1,7,2.5,-5,M,37,M,,*5D
\$OSGBS,183431.00,0.5,0.5,1.2,09,,161.3,103.1*41
\$FUVTG,,T,322.1,M,0.1,N,0.1,K*62
\$RAMWV,188.4,T,005.9,N,A*21
\$FUZDA,183431,19,04,2016,-2,0*62
\$FURMC,183431,A,5215.2861,N,00522.8963,E,0.1,323.1,190416,1,E*63
\$GPZDA,183431,19,04,2016,0,0*4D
!OSVDM,1,1,,A,13aDC:0P00PHI@nMr:dWqwwv2<0;,0*52
\$FURMB,A,0.00,R,START,000F,314.229,N,00511.209,E,59.5,353.2,0.0,V*75
\$OSGGA,183432.00,5215.28837,N,00522.89619,E,2,10,0.80,-
0.6,M,46.0,M,,0000*7F
!OSVDM,1,1,,A,13`hBUOP00PI3k6MppFnQ?vv26B8,0*26
\$RAHDG,196.0,,,, *54
\$RADPT,0.7,0*4A
\$RAVHW,,T,196.0,M,0.0,N,,, *2F
\$FUGLL,5215.2862,N,00522.8962,E,183432,A*28
\$RAVWR,172.5,R,5.9,N,,,, *51
\$RAMWV,172.5,R,5.9,N,A*23
\$OSGLL,5215.28837,N,00522.89619,E,183432.00,A,D*6C
\$FUGGA,183432,5215.2862,N,00522.8962,E,1,7,2.5,-5,M,37,M,,*5C
\$OSGBS,183432.00,0.5,0.5,1.2,,,, *4D
\$FUVTG,,T,322.8,M,0.1,N,0.1,K*6B
\$RAMWV,172.6,T,005.9,N,A*26
\$FUZDA,183432,19,04,2016,-2,0*61
!OSVDO,1,1,,B3aL>PP0086::A7NJ3CQ3wh5oP06,0*7A
\$FURMC,183432,A,5215.2862,N,00522.8962,E,0.1,323.8,190416,1,E*6B
\$GPZDA,183432,19,04,2016,0,0*4E
\$FURMB,A,0.00,R,START,000F,314.229,N,00511.209,E,59.5,353.2,0.0,V*75
\$OSGGA,183433.00,5215.28836,N,00522.89621,E,2,10,0.80,-
0.7,M,46.0,M,,0000*75
\$RADPT,0.7,0*4A
\$RAVHW,,T,196.0,M,0.0,N,,, *2F
\$FUGLL,5215.2862,N,00522.8962,E,183433,A*29
\$RAVWR,160.0,L,5.9,N,,,, *49
\$RAMWV,200.0,R,5.9,N,A*20
\$OSGLL,5215.28836,N,00522.89621,E,183433.00,A,D*67
\$FUGGA,183433,5215.2862,N,00522.8962,E,1,7,2.5,-5,M,37,M,,*5D

\$RAMWV,199.7,T,005.9,N,A*22
\$OSGBS,183433.00,0.5,0.5,1.2,,,,*4C
\$FUVTG,,T,323.4,M,0.1,N,0.1,K*66
\$FUZDA,183433,19,04,2016,-2,0*60
\$FURMC,183433,A,5215.2862,N,00522.8962,E,0.1,324.4,190416,1,E*61
\$GPZDA,183433,19,04,2016,0,0*4F
\$FURMB,A,0.00,R,START,000F,314.229,N,00511.209,E,59.5,353.2,0.0,V*75
\$RAHDG,196.0,,,,*54
\$OSGGA,183434.00,5215.28838,N,00522.89619,E,2,10,0.80,-
0.8,M,46.0,M,,0000*78
\$RADPT,0.7,0*4A
\$RAVHW,,T,196.0,M,0.0,N,,,*2F
!OSVDM,1,1,,B,13aJIGPP0PPHH3nMnvIt5ww426B8,0*78
\$FUGLL,5215.2863,N,00522.8962,E,183434,A*2F
\$RAVWR,165.5,R,5.9,N,,,,*57
\$RAMWV,165.5,R,5.9,N,A*25
\$OSGLL,5215.28838,N,00522.89619,E,183434.00,A,D*65
\$RAMWV,165.5,T,005.8,N,A*22
\$FUGGA,183434,5215.2863,N,00522.8962,E,1,7,2.5,-5,M,37,M,,*5B
\$OSGBS,183434.00,0.5,0.5,1.2,,,,*4B
!OSVDM,1,1,,B,13aEPH0P010I5rHMpWS0Aww2PL0A,0*44
\$FUVTG,,T,323.9,M,0.1,N,0.1,K*6B
\$FUZDA,183434,19,04,2016,-2,0*67
!OSVDO,1,1,,,B3aL>PP0086::A7NJ3CQ3wi5oP06,0*7B
!OSVDM,1,1,,A,13aGFOhP00PI1f6MqQsT7gvr26B8,0*2B
\$FURMC,183434,A,5215.2863,N,00522.8962,E,0.1,324.9,190416,1,E*6A
\$GPZDA,183434,19,04,2016,0,0*48
\$FURMB,A,0.00,R,START,000F,314.229,N,00511.209,E,59.5,353.2,0.0,V*75
\$RAHDG,198.0,,,,*5A
\$OSGGA,183435.00,5215.28841,N,00522.89611,E,2,10,0.80,-
0.8,M,46.0,M,,0000*7F
\$RADPT,0.6,0*4B
\$RAVHW,,T,198.0,M,0.0,N,,,*21
\$RAVWR,169.0,R,5.9,N,,,,*5E
\$FUGLL,5215.2864,N,00522.8962,E,183435,A*29
\$RAMWV,169.0,R,5.9,N,A*2C
\$RAMWV,169.0,T,005.8,N,A*2B
\$OSGLL,5215.28841,N,00522.89611,E,183435.00,A,D*62
\$FUGGA,183435,5215.2864,N,00522.8962,E,1,7,2.5,-6,M,37,M,,*5E
!OSVDM,2,1,1,A,53aDpG4000010KCSST1aDTB0Pthh4p@00000001?5`:42t@PJ33@Dm80@j
51,0*4D
\$FUVTG,,T,323.9,M,0.0,N,0.0,K*6B
!OSVDM,2,2,1,A,DSP@0000000,2*22
\$OSGBS,183435.00,0.5,0.4,1.2,,,,*4B
\$FUZDA,183435,19,04,2016,-2,0*66
\$FURMC,183435,A,5215.2864,N,00522.8962,E,0.0,324.9,190416,1,E*6D
\$GPZDA,183435,19,04,2016,0,0*49
\$RAHDG,198.0,,,,*5A
\$FURMB,A,0.00,R,START,000F,314.229,N,00511.209,E,59.5,353.2,0.0,V*75
\$OSGGA,183436.00,5215.28841,N,00522.89610,E,2,11,0.78,-
0.6,M,46.0,M,,0000*75
\$RADPT,0.6,0*4B
\$RAVHW,,T,198.0,M,0.0,N,,,*21
\$RAVWR,167.5,R,5.9,N,,,,*55
\$RAMWV,167.5,R,5.9,N,A*27
\$FUGLL,5215.2864,N,00522.8962,E,183436,A*2A
\$RAMWV,167.4,T,005.9,N,A*20
\$RAHDG,198.0,,,,*5A