



Serve over with tape.



Lead strand and, if required, insert thimble. Pull each part back to  
and lay up together spalling round the standing part.