



**Steel hull without anode
leading to galvanic corrosion**




Steel hull with Zn anode closed loop but no corrosion because of protecting anode



Polyester hull without anode
no closed loop > no corrosion

electrons flow not possible through polyester
no charges separation possible
>>> no galvanic corrosion



Polyester hull with anode
 connected to skin fitting and keel
 closed loop but no corrosion because of protecting anode

